

1. Roads / Sidewalks

- a) Remove windrows and piles of snow causing problems for residents
- b) Keep culverts steamed & ditches flowing, push windrows away from ditches to stop blockages

2. Water/Wastewater

- a) 46 St main break by EMS located, and asbestos cement line repaired; curb stop replaced, samples taken
- b) Portable cl₂ analyzers recertified & calibrated
- c) Thawed frozen service at old Dehid motors as per request
- d) Gel standard tests a pumphouse
- e) Worked on frozen service – unable to thaw, resident left to Mexico for 5 weeks
- f) Steamed & Vac'd Sunshine Reflexology cc valve but line frozen and unable to access with pulsator due to crimped lines
- g) Steamed & Vac'd Hryciw Plumbing frozen sewer line
- h) Thawed Public Works sewer line
- i) Vac'd PVR Vault and flushed sanitary mains; 45 Ave east & 53 St North
- j) Thawed sewer line at Centennial Hall
- k) Deliver water to resident due to frozen service
- l) Monitor southside water pressure
- m) Unusual flow rates at pumphouse monitored until returned to normal
- n) Update bacti and Gel Standard Logbooks as per Alberta Environment Inspection
- o) Fire extinguishers, emergency lights checked at reservoir, Pumphouses & Lift Station
- p) Bacti & Additional sample taken as per operator request
- q) Unable to thaw water service at 5204 48 st due to old pulsator line broke off in line
- r) Unable to thaw Zayak rental house temporary service installed
- s) Ordered 300' pulsator line to attempt to thaw Charleston service under Highway 36
- t) Thawed reservoir pumphouse sanitary line
- u) Sandbagged storm drain catch basin at EMS to prevent storm water from entering main break excavation until storm line repaired
- v) Calibrate pumphouse cl₂ monitors
- w) Monitoring increased flows at sanitary lift station

3. Other

- a) Took down decorations along highway and main street. Unplug rope lights. Could leave up or remove to save from weathering & fading
- b) Single Axel gravel truck & Vac truck due for inspection March 31 2019