



Roads / Sidewalks

- a) Grade all roads and back alleys
- b) Grade now off parking area in the cemetery
- c) Grade snow off south side of the old rail bed for snow dumping
- d) Apply beet juice to all icy roads and intersections

Water/Wastewater

- a) The Town experienced no power disruptions since last report - all systems good
- b) Furnace failure at lift station - gas valve ordered and replaced by Nordic
- c) Pumphouse and lift station housekeeping
- d) Continue to monitor pressure and flow rates
- e) Check well house furnace
- f) Check reservoir furnaces
- g) Lift station generator test
- h) Annual AB ENV reporting completed and submitted
 - a. water works
 - b. waste water
 - c. well water
 - d. lead management
- i) Internet disruption at Reservoir pumphouse - still no service
- j) 2 residential services shut off at CC, after water breaks due to freezing
- k) APEX gas valve at reservoir failed - preventing Natural Gas from entering pumphouse to run furnaces and emergency stand by pump, repaired by APEX & furnaces relit.
- l) Natural gas standby engine started and tested
- m) Installed new air relief valve on lag pump #3 at reservoir
- n) Contacted Aqua Clear to quote on anerobic cell dewatering and dredging at lagoon system
- o) Water break at Cenotaph - circular break repaired under positive pressure 4 x 16 stainless repair clamp. Water restored in 24 hours
- p) Flushing, testing and reporting completed ad per code of practice

Other

- a) Install new 17 HP engine on sand box
- b) Install snow blower on New Holland tractor to remove snow drifts off sidewalks
- c) Service all snow removal equipment
- d) Complete all service requests

Note: Public works continues to use Covid 19 Best Practices and standard procedures when dealing with the public and during property entry during the performance of water/ wastewater duties

