

Roads / Sidewalks

- a) Grade 55 Ave, 51 St north of highway 45
- b) Grade 46 Ave west of 54 St
- c) Grade Back alleys
- d) Apply beet juice to major intersections and roads
- e) Grade ice and packed snow off 47 Ave, 48 Ave and intersection 46 St & highway 45

Water/Wastewater

- a) The town experienced 1 power disruption since last report - short power failure affecting the sanitary lift station and Reservoir pumphouse - all systems good
- b) Gel standard tests and cl2 analyzer calibrations done
- c) Shut off residential water service as per request
- d) Continue to monitor pressure and flow rates
- e) VFD (variable frequency drive) replaced at Reservoir
- f) Month end water meter reads
- g) Began installing new meter registers and transmitters in commercial properties
- h) Manhole check on 57 Street
- i) Generator test at lift station
- j) Engine driven pump tested and programming checked
- k) Fire hydrant winterizing completed
- l) Continue working on AB ENV annual reporting
- m) Monitor lagoon release
- n) Pressure and flow alarms after fire dept used hydrant on corner of 50th Street and 47th Ave
- o) Water break on 48th Ave, excavated, repaired and tested

Other

- a) Remove damage guard rail and broken posts from the corner of 46 St & 47 Ave
- b) Install new rear ties and new batteries on the grader
- c) Install snow fence along highway 36 on east and west side on old rail line
- d) Dig trench for electric conduit at the hall
- e) Sweep sidewalks and spread salt
- f) Service and repair sidewalk sweeper (New Holland)
- g) Complete all service requests

Note: Public Works continues to use Covid 19 Best Practices and Standard Procedures when dealing with the public and during property entry for the performance of Water / Wastewater duties.

